
27 Signal Hill Dr

Survey with trees marked







Tree #1 – Dead

Tree #2 - Dead



Tree #3 – 90% dead and leaning

Tree # 4 – very close to and leaning towards the house

Tree #5 – close to house and leaning